



[illegible]

FIG.



006221" 09525/60

FIG.





FIG. 4



0052350-12940  
006221-09535/60

FIG. 5




FIG 6









FIG. 7



(a)




(b)




005536 1-2000



FIG. 9



(a) OBSTRUCTION OF ATTACHED FINE PARTICLES AGAINST NORMAL DEPOSITION



(b) ABRASION OF DEPOSIT SURFACE BY FINE PARTICLES

FIG. 10




FIG. 11

